FIGURE 2
SITE LAYOUT MAP
SERVICE OIL COMPANY, INC.
ELROY, WISCONSIN

METCO

SCALE:
1 INCH = 48 FEET

NOTE: INFORMATION BASED ON AVAILABLE DATA. ACTUAL CONDITIONS MAY DIFFER.

▲ - TANK CLOSURE SAMPLE LOCATION (METCO)
• - TANK CLOSURE SAMPLE LOCATION (MARELL)
- SOIL BORING LOCATION (MADDEN OIL)
- MONITORING WELL LOCATION (MADDEN OIL)
- MONITORING WELL LOCATION
TELEPHONE POLE
SEWER MANHOLE
WATER VALVE BOX
FIRE HYDRANT
STORM SEWER GRATE

FORMER TANK SYSTEMS INCLUDE THE FOLLOWING:

A - 17,000 GALLON UNLEADED AST
B - 15,000 GALLON UNLEADED (FORMERLY LEADED) AST
C - 12,000 GALLON UNLEADED (FORMERLY LEADED) AST
D - 17,000 GALLON DIESEL AST
E - 12,000 GALLON #2 FUEL OIL AST
F - 12,000 GALLON #2 FUEL OIL AST
G - 500 GALLON UNLEADED GASOLINE UST
H - 300 GALLON DIESEL AST
I - 1,000 GALLON KEROSENE AST
J - 1,000 GALLON #1 FUEL OIL AST

NOTE: TANKS A-F HAVE BEEN OUT OF SERVICE SINCE 2001. TANK G WAS REMOVED IN 1999, AND TANKS H, I, AND J WERE REMOVED IN THE EARLY 1990'S

TANK CLOSURE SITE ASSESSMENT RESULTS (METCO 4/6/93)

S-1 - 18,000 PPM DRO AND 3,100 PPM GRO AT 2-3 FEET
S-2 - 25 PPM DRO AND 110 PPM GRO AT 2-3 FEET

TANK CLOSURE SITE ASSESSMENT RESULTS (MARELL 12/16/99)

SAMPLE #1 - 2,800 PPM GRO AT 5-6 FEET
SAMPLE #2 - 8,600 PPM GRO AT 1-2 FEET



Proposed Locations
X = Soil boring
⊗ = monitoring well/ piezometer.

\\Service Oil Co B.P.-C149\Vcadd\C149slm3.vcd 10/8/2002