

NOTES

1) All dimensions and locations are approximate and are based on limited field measurements by REA field personnel and aerial photographs.

2) See Figure 1 for site location relative to Oregon, Wisconsin.

3) Geoprobe soil borings B-1 to B-8 advanced on May 17, 2002, by Soil Essentials, New Glarus, WI.

4) Monitoring wells MW-1 to MW-4 installed on October 29, 2002 by Soil Essentials, New Glarus, WI.

5) Geoprobe soil borings B-101 to B-109 advanced on October 28, 2002, by Soil Essentials, New Glarus, WI.

6) Monitoring wells MW-4A, MW-5 to MW-8 and soil boring B-201 installed on July 1-2, 2003 by Soil Essentials, New Glarus, WI.

7) Monitoring wells MW-4B, MW-9 and MW-10 installed on November 11, 2003 by MES, Waukesha, WI.

REVISIONS:

RESOURCE ENGINEERING ASSOCIATES, INC.
Resource Engineering Associates, Inc.
8505 University Green
Suite 200
Middleton, Wisconsin 53562-2507
P: 608-831-6563 F: 608-831-6564

EXTENT of RESIDUAL CONTAMINATION in SOIL EXCEEDING NR746.06 TABLES 1 & 2 in the TOP 8 FEET
PIERSON PROPERTY
998 JANESVILLE STREET, OREGON, WI

Date: Jan. 2005
Drawn: SKB
Checked: WWB
Drawing # pierson12.dwg
Project # 020021.4

FIGURE 5

2001 © RESOURCE ENGINEERING ASSOCIATES, INC.